

[2024-07-05 09:04:28.874] Asterisk 20.8.1+asl3-3.0.0-1.deb12 built by builder @ allstarlink.org on a aarch64 running Linux on 2024-06-13 23:09:36 UTC
[2024-07-05 09:04:28.918] NOTICE[932] loader.c: 70 modules will be loaded.
[2024-07-05 09:04:29.166] NOTICE[932] cdr.c: CDR simple logging enabled.
[2024-07-05 09:04:29.169] NOTICE[932] dnsmgr.c: Managed DNS entries will be refreshed every 300 seconds.
[2024-07-05 09:04:29.194] NOTICE[932] indications.c: Default country for indication tones: us
[2024-07-05 09:04:29.194] NOTICE[932] indications.c: Setting default indication country to 'us'
[2024-07-05 09:04:29.284] NOTICE[932] res_smdi.c: No SMDI interfaces are available to listen on, not starting SMDI listener.
[2024-07-05 09:04:29.298] WARNING[932] chan_dahdi.c: Only FX0 signalled channels may belong to a call group
[2024-07-05 09:04:29.298] WARNING[932] chan_dahdi.c: Only FX0 signalled channels may belong to a pickup group
[2024-07-05 09:04:29.298] NOTICE[932] chan_dahdi.c: Ignoring any changes to 'userbase' (on reload) at line 23.
[2024-07-05 09:04:29.298] NOTICE[932] chan_dahdi.c: Ignoring any changes to 'vmsecret' (on reload) at line 31.
[2024-07-05 09:04:29.298] NOTICE[932] chan_dahdi.c: Ignoring any changes to 'hassip' (on reload) at line 35.
[2024-07-05 09:04:29.298] NOTICE[932] chan_dahdi.c: Ignoring any changes to 'hasiax' (on reload) at line 39.
[2024-07-05 09:04:29.298] NOTICE[932] chan_dahdi.c: Ignoring any changes to 'hasmanager' (on reload) at line 47.
[2024-07-05 09:04:29.298] WARNING[932] chan_dahdi.c: Only FX0 signalled channels may belong to a call group
[2024-07-05 09:04:29.298] WARNING[932] chan_dahdi.c: Only FX0 signalled channels may belong to a pickup group
[2024-07-05 09:04:29.497] WARNING[932] loader.c: Module 'res_adsi' has been loaded but may be removed in a future release.
[2024-07-05 09:04:29.599] NOTICE[1035] app_rpt.c: Normal Repeater Init 585244
[2024-07-05 09:04:29.603] NOTICE[1039] chan_simpleusb.c: Channel 585244: Set option TONE VERIFY, mode: OFF(0).
[2024-07-05 09:04:29.679] WARNING[1039] chan_simpleusb.c: Possibly stuck USB read channel. [585244]
[2024-07-05 09:04:29.705] WARNING[1039] chan_simpleusb.c: USB read channel [585244] was not stuck.
[2024-07-05 09:05:52.005] ERROR[1039] chan_simpleusb.c: Channel 585244: HID process has died or is not responding.
[2024-07-05 09:05:52.842] WARNING[1035] app_rpt.c: rpt_thread restarted on node 585244
[2024-07-05 09:05:52.844] NOTICE[1308] chan_simpleusb.c: Channel 585244: Set option TONE VERIFY, mode: OFF(0).
[2024-07-05 09:05:52.872] ERROR[1309] chan_simpleusb.c: Channel 585244: Unable to open DSP device 1: Device or resource busy.
[2024-07-05 09:05:56.003] ERROR[1308] chan_simpleusb.c: Channel 585244: HID process has died or is not responding.
[2024-07-05 09:10:42.032] NOTICE[1016] dnsmgr.c: dnssrv: host 'register.allstarlink.org' changed from 162.248.92.131:443 to 34.105.111.212:443